

Adhesive bonding: not suitable for disassembly, difficult to repair, corrosion resistant, air and water tight, loaded only transversely (shear stress).

Annealing: part of a heat treatment

Autoclave cycle: costs a lot. It gives higher fiber volume fraction; current engineering matrices need high temperatures.

Back pressure: additional pressure over the entire part

Barreling: the cross-sectional size near the dies tend to increase less than the cross-sectional size in

Batch: number of parts, processed and handled as group

Beech Starship: Sandwich skin and monocoque lay out

Beveling: placing the punch under an angle to control the shear location

Billet: initial (starting) material during for instance extrusion

Blanking: the slug is the part and the rest is scrap

Blank-holder: device that holds the sheet during the process, prevent sheet buckling (deep drawing)

Bleeder: layer that stores/absorbs excess of resin (autoclaving)

Bleeder layer: sees to it that the breather layer is not filled up with resin and that superfluous resin is absorbed.

Breather: layer in composite manufacturing. Makes sure that air can leave the composite product during processing

Breathing: the escape of air from moulds (compression molding)

Breather layer: sees to it that the transport of air is guaranteed during the whole process

Casting: melting & pouring, (injection molding, die casting, lost wax casting). Limit: special alloys, properties after casting

Casting factor: a safety factor, originating from uncertainties in material properties. A Casting factor of two for a non critical structural part means that no tests need to be performed for the certification of the part.

Cavity: bottom section of the mould (compression molding)

Cellular manufacturing: the approach in which equipment and workstations are arranged in a sequence (cells = families)

Charge: mix of reinforcement resin

Chisel: the tool that actually removes the chip from the workpiece

Chill: local cooling

Chips: pieces removed from the workpiece during machining (turning)

Climb milling: Movement direction workpiece and tools is the same

Conventional milling: Movement direction workpiece and tools is the opposite

Cope: top part of the mould

Cutting fluid: lubrication and cooling

Damage tolerance: means that you inspect on a regular basis

Deburring: removing sharp debris (burrs) from work piece (drilling)

Deformation by (viscous) flow: the viscous flow is the deformation occurring when a material is behaving as a thick viscous fluid. It often occurs due to heating.

Die: opening that determines the shape of the product

Dislocation: an imperfection in a metal lattice (bending), misalignment in crystal lattice (forging)

Delivery interval: time interval between the delivery of two subsequent aircraft

Diffusion-bonding: creation of a bond between two metal surfaces squeezed at high temperatures by means of atomic diffusion and migration

Drag: bottom part of the mould

Dross: foam, a material with very many air inclusions. Originating during the casting process as a result of turbulent flow (Casting)

Dynamic process: it is developed over time and will continuously evolve

Dry-spot: non impregnated areas after resin is added

Douglas DC2: A brilliant example of new technology converted into a successful design, NO sandwich, aluminum stressed skin as structure of the fuselage

Fail-save: multiple load paths

Flank: surface of the material of the chisel located between chisel and workpiece (turning)

Flapping: movement of work piece when not properly clamped (machining)

Flash: a thin flat piece of metal attached to the product after forging. It needs to be trimmed off.

Flask: support for the mould (impression die molding)

Flange: part of sheet that remains under blankholder (deep drawing)

FML: FML's do not have good forming capabilities due to the presence of fibres with a low strain to failure. Cutting processes for FML's like drilling, milling, etc are about the same as for conventional aluminum alloys.

Fokker XII: No sandwich, wooden wing, NO pressurized fuselage, steel truss structure as fuselage. Not comparable with DC2 and mosquito

Force: top section of the mould (compression molding)

Forgeability: the ability of the material to endure a permanent (plastic) deformation.

Forming: Plastic deformation by force (bending, deep drawing, press forming). Limit: force and size

Gap: the clearance between the punch and the drawing die (deep drawing)

Gates: part of the running system

Geodesically: the reinforcement takes the shortest route from one point to another the middle of the workpiece.

Grinding: chip-removal process that uses an individual abrasive grain. Blunt and negative tool angle

Heat treatment: annealing, ageing, quenching; After unstable heat treatments, the parts should be further processed within a limited time frame.

Heel-line: the intersection of the tangent to the web plate and the tangent to the flange

Helical winding: winding under other angles

Hoop winding: winding under 90 degree angle

Hot tears: small cracks caused by the fact that the specimen couldn't shrink

Isotropic: Properties of a material depend on the direction. Properties of a material are identical in all directions

Inter-ply: slip of prepreg layer, flat cross sections do not stay flat

Jigs: these are in principle scaffolds, in which the parts are fastened at their positions and joined to create larger parts. They can rotate and are separable. Very stiff to minimize deflections. Accessible to ease the assembly. Strong to carry all the loads

J.I.T: producing the right items at the right time in exactly the right amounts (no storage)

Jetlag: Bending of the beam of water originating from the movement of the beam itself

Kerf: Narrow zone that is removed from the workpiece

Knit-lines: merging of the flow fronts can occur, the reinforcement can't cross such lines, and therefore parts without reinforcement will occur

Lathe: turning machine

Life length: the distance which cutting tools can cut before they become blunt (drilling)

Life amount: the amount of products that can be produced before the cutting tools become blunt

Loal leveling: leveling out the amount of products to the need of the consumer (equal work load for workers and machines)

Learning curve: regression curve expressing the decreasing amount of time required for a particular task when performed over and over again.

Lean manufacturing: continuously optimizing and using the flow of information and materials in the manufacturing environment in such a way that enhanced value (lower costs) are achieved (Minimal tooling, simple clamping devices).

Key elements of LM: Waste (should be eliminated), Value creation (main focus), increasing the value of the part by manufacturing activities, Knowledge, Dynamic (ever continuing)

Machining: removing material (chipping/cutting), milling, sawing, drilling. Limit: complexity, wall thickness

Mandrel: mould for winding where the reinforcement is wound onto.

Manufacturing division: A division originating from a manufacturing point of view. This can originate from work load distribution, manageability, etc...

Micro porosity: high thickness, outside can solidify sooner than the inside, small cavity occurs

Moulding compound: mix of reinforcement resin

Mosquito: stressed skin, efficient wooden construction, sandwich fuselage, top of its capabilities, WWI

Nesting: the skillfully positioning of the needed blanks in a large sheet (blanking)

Nesting: by nesting property the lost material (scrap) is minimized, placing as many parts as possible

NDI: A test for the evaluation of a material or part without compromising the quality or functionality

Nibbling: a nibbler moves a small straight punch up and down rapidly into a die (curved cutting)

Out-of-jig: drilling/making holes before assembly → more accurate

Parting-line: seam between cope and drag

Pattern: replica of the desired product used for making the mould

Peel-ply: (scheurlaag) enables the possible removal of the bleeder layer, sees to it that an adhesive bonding is feasible

Permeability: the easiness at which a stream (liquid or gas) flows through a material (RTM)

Plasma: thermally highly heated up, electrically conductive gas, which consist of positive and negative ions, electrons as well as excited and neutral atoms and molecules. Fourth state of material (plasma arc cutting)

Plastic deformation: the deformation where on micro level metal lattices move due to shear. This is possible as there are faults in the lattice, such as dislocations.

Porosity: the amount of emptiness in a material. (voids) .. (RTM)

Pot-life: the time until the viscosity of the resin starts to change

Pouring basin: molten metal is poured in

Polar winding: winding under 0 degree angle

Profile: the billet after it has passed the die

Preform: reinforcement shaped in shape of the mould

Pre stress: (pre-tensioning) increases the average stress, but lowers the stress amplitude. The stress amplitude causes more damage during fatigue of an aircraft than the average stress.

Production rate: More stations and the workload per station is low

Push market: the producer has most influence on the product

Punching: the sheared slug is discarded, removing a part of the sheet by punching it

Quenching: part of a heat treatment (fast cooling) (rubber forming)

Rake/face: the area of the cutting tool on which the chip pushes

Rake angle: angle between cutting edge of tool and normal of the work piece surface (turning)

Relief angle: Angle between flank of tool and the work piece (turning)

Reel: initial material in the shape of bobbin (spool). The roving is wound on it (filament winding)

Residual stresses: remain in the part after spring-back

Risers: supply additional metal to the casting as it shrinks during solidification. Open riser-: See if the mould system is filled, act as buffer or as a vent

Riviting: simple, easy to repair, never in tensile loading, sensitive to corrosion and fatigue

Rovings: untwisted bundles of continuous filaments

Runners: channels along which the resin can flow relatively easily

Running system: channels to transport the metal to the mould cavity

Saddle back: bend deformation of narrow strip, tension side wider, compression side smaller (bending)

Shape factor: Gives an indication for the complexity of the product; perimeter/cross sectional area

Shrinkage/casting allowance: the increase of the mould cavity to compensate for shrinkage

Shunt: bypass in the production line due to excess of work package (double)

Sink mark: Dimple in surface opposite to a stiffener element due to shrinkage (casting)

Station: stage in production where the same people perform the same tasks in the same amount of time

Strain-hardening: during plastic deformation the dislocation density often increase with increasing deformation

Stiffening bead: A local deformation/indentation to improve the bending stiffness of a flat sheet

Sprue: metals flows downwards

Slug: material that is removed during punching (forging)

Slab milling vs. force milling: parallel to and perpendicular to machined face

Stressed-skin: The principle that a structure can be made such that all mass- and air forces can be carried by the skin.

Swell: occurs when the polymer exits the extruder, because of the low stiffness

Tool angle: Angle between flank and rake face of a chisel (machining)

Turning: positive tool angle (sharp)

Thermoset: mould hotter than material, when formed material needs to cure, so higher temperature is needed to decrease curing time.

Thermoplastic: material is hotter than mould, when forming material needs to cure, so certain temperature is needed, after flowing material needs to become rigid, temperature needs to be lowered. Thermoplastics can be melted down and moulded into something different. Short product cycle.

Trellis effect: causes an local increase in the thickness of the fabric, intra-ply shear, the fibres orientate differently with respect to each other.

Universal process: process that is applied to a wide range of different parts

Vacuum bagging film: film to close the laminate from the outside

Value stream mapping: A lean manufacturing technique used to analyze the flow of materials and information currently required to bring a product or service to a consumer.

Vents: transport gasses and hot air from the mould

Viscous: easiness with which a liquid flows (RTM)

Voids: hollow section in a extrusion

Warp: caused by internal stresses

Waste: anything that uses resources but does not create value; material waste, supplies, waiting period for man and machine, transport, unnecessary movements.

Wrinkle: fold in a sheet material (deep drawing)

Winding angle: angle under which the fibers are wound

Yarn: a collection of filaments, often entangled (filament winding)

Quality policy:

Overall intentions and directions of an organization with regard to quality, as formally expressed by top management

Quality planning:

Activities that establish the objectives and requirements for quality and for the application system elements.

Quality control:

Operational techniques and activities that are used to fulfill requirements for quality

Quality assurance;

All the planned and systematic activities implemented within the quality system, and demonstrated as needed to provide adequate confidence that an entity will fulfill requirements for quality.

Quality:

The totality of characteristics of an entity that bear on its ability to satisfy stated and implied needs.

Quality management:

All activities of the overall management function that determine quality policy objectives and responsibilities and implement them by means such as quality planning. Quality control, quality assurance and quality improvement within the system.

Quality plan:

Document setting out and the specific quality practices, resources and sequences of activities relevant to a particular product or contract.

Quality Audit:

Systematic and independent examination to determine whether quality activities and related results comply with planned arrangements and whether these arrangements are implemented effectively and are suitable to achieve objectives.

Quality system:

Organizational structure, procedures, processes and resources needed to implement quality management.

Non destructive testing:

Ultrasonic: detect inclusions, voids, delamination

Eddy current: Cracks, uniformity of heat treated materials (NOT for composites)

Penetrant: Metals, detect open-to-face cracks

Computer aided tap test: detect delaminations in composites

Process focused: inspection is performed regularly throughout the production process

System focused: Improving and checking on the quality of the work floor

Product focused: A check is performed when the product is completed

5S:

Sort: sorteren van goede en slechte dingen (onnodige dingen)

Simplify: alles ordenen in logische volgorde

Scrub: clean and maintain

Standardize: the continuously improved methods need to be documented and followed

Stress/strain diagram:

Elastic area, uniform deformation, necking area (defuse necking), local necking up to failure

Casting:

A process in which molten metal is poured into a mould, after which they are cooled and separated. Casting is often cheaper than forging. However, the mechanical properties of cast products are usually less. Also the minimal achievable thickness of forged products is smaller.

Investment casting

If the pattern is not made from metal but from wax, the process is called lost-wax process or **investment casting**. After mould creation, the wax can be reused. Create wax products, coat it with ceramics, melt wax, pour liquid metal, shake ceramics mould in pieces (trees). Thin walls possible, freedom geometry, suitable for small amount of products.

Compression Molding (lijkt op forging)

Most of all composite components are produced using compression moulding. In this manufacturing method a compressive force is applied to a mix of reinforcement and resin. This mix then flows between two mould-halves. After that, the mould is opened only slightly for a few seconds to allow formed gasses to escape.

Large freedom of design, short production time and high accuracy

Extrusion

Extrusion is a process in which a heated metal billet is squeezed through an opening, called a die. This die is just a thin disk. In this way a long profile is created. Since the grains of the metal are stretched, extruded materials are usually anisotropic. Extrusion is a semi-continuous process, since a new billet needs to be inserted once in a while.

Filament Winding

The filament winding process covers the wrapping of a mould (mandrel). The fibres are bundled as rovings on a reel, which is unrolled during filament winding. During wet winding the fibre bundels are pulled through a resin bath, followed by wet placement on the mandrel. As soon as the whole product is covered with fibres the fibre-resin and mandrel are cured. This is followed by the removal of the mandrel. Some finishing operations might be needed to create the final product.

Forging (compared best to compression molding; a shapeless material is pressed into a certain shape)

Forging is a process in which the workpiece is shaped by compressive forces. The workpiece, called slug, billet or preform is metal, as composites cannot be forged. Also, not all metals are suitable for forging. The metal is placed between two dies, which are then pressed together. The material is then deformed to the desired shape. During pressing, barreling may occur.

Lay-up

Lay-up is the term used for placing fibre-reinforced polymers in a mould. First the individual reinforcement is profiled and cut to the right shape. From this, layer by layer, a laminate is made. Lay-up is always followed by other processes.

Pultrusion

Composites cannot be extruded. So for composites pultrusion is used. The pultrusion process combines fibres and resin into a composite product. By transporting the fibres through the resin, and subsequently through a mould in which the resin is cured, a continuous product with a uniform cross-section is obtained. The size of the cross-section of the product is dependent on the machine but can in principle be very large since only low forces are needed during the process. This is because the mould needs to guide and cure the resin.

RTM (only composite structures can be made)

Resin transfer molding (RTM) is the term used to describe a range of closed-mould low-pressure processes. In RTM processes the reinforcement fibers are put in the mould before the resin is added. Close the mould. Let the resin flow through the fibers and then cure the resin. Since the process is closed, personnel will not be exposed to hazardous vapours. The main advantage of RTM is the capability to rapidly manufacture large, complex, high-performance structures.

Rubber forming:

Metal sheet deforming process in which a pre-shaped undeformable mould and rubber mould are applied. The rubber mould pushes the metal sheet over the pre-shaped undeformable mould. This last shapes the product.

Bending:

Bending is one of the most common processes for manufacturing simple elements. We can describe bending by using a simple model. This model is based on various assumptions. Among others, we assume that the bending is performed by a pure bending moment and that the bend radius is constant everywhere in the bend zone. When bending a material, there will be both elastic and plastic deformation. Upon release, this elastic deformation will cause spring back. Isotropic, homogeneous, flat planes remain flat, congruent stress-strain curve, no internal stresses.

Forming of Fiber Reinforced Thermoplastics

The deformation mechanisms applicable on an FRTP highly depend on the fibers used. If short/medium fibers are used, then the fibers will flow within the resin. The resin will dominate the forming. If, however, long/continuous fibers are used, the fiber reinforcement will dominate the forming. Often intra-ply shear (the so-called Trellis effect) will be used. This causes the fibers to orient differently with respect to each other. Previously orthogonal fibers may not be orthogonal anymore. Sometimes, in the case of a laminate (a stack of layers) also inter-ply slip can be used. Now the different layers will slip with respect to each other.

Deep drawing:

Deep drawing is a process using a punch to stamp a metal sheet to the desired shape. First a metal blank is clamped between a die and a blank holder. The metal blank should be free to move between the die and the holder (often a lubricant is used for that), but it should not be able to wrinkle. Then a punch is used to give the metal blank the desired shape.

Rubber forming:

Rubber forming is a press forming process using a soft rubber press and a rigid die. The die (usually made from laminated wood) is placed into the press. The metal blank is placed on top of it. The rubber pad is then pressed on the die, forming the metal blank. Instead of a solid rubber pad, also a fluid cell, enclosed by a rubber membrane, can be used for pressing.

Sheet forming:

Sheets are usually used by the concept of forming. This term is mainly used to express the deformation of a material. The materials are manipulated such that the required shape is obtained. This can be done with multiple techniques, depending on the material you are using.

Stretch forming:

Stretching or stretch forming is a process used to manufacture large and slightly **double curved shells**. Here bending and stretching of a metal sheet are combined in one process. First the tensile forces will stretch the material such that the sheet is deformed plastically. Then a die is pressed into the sheet causing it to stretch even more, but also to bend.

Superplastic forming: stable grains and high forming temperatures, low strain rates

Superplastic forming (SPF) is a rather unconventional forming process. During normal plastic forming the crystals of the metal alloy are deformed. In superplastic forming the crystals simply slide along each other at high temperatures. The prefix super means that very high deformations can be reached (often 30 times greater than normal). This also happens at very low forces. Gas pressure is usually enough to reach the desired deformations.

Vacuum infusion process:

Hard mould is used. On this mould dry weaves/fibers are placed. This is followed by the application of a foil, which is applied to be able to create a vacuum around the reinforcement. The next step involves the adding of resin. The resin is sucked by the vacuum through the reinforcement. After curing and demoulding the product is obtained.

Turning process:

The work piece is rotating; the chisel is moving toward the work piece and removing material. Often rotational symmetrical shapes.